



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

---

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-132	Smoke	10/22/2008	ADS/TM	S13GG_032MH	Dry	Yes	1,650.27

### Isolated Pipes

---

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13GG_043G2	S13GG_043MH	S13GG_039MH	52.85442	8
S13GG_032G1	S13GG_032MH	S13GG_036MH	121.5937	8
S13GG_005G1	S13GG_005MH	S13GG_017MH	96.18813	18
S13GG_036G1	S13GG_036MH	S13GG_010MH	70.34773	18
S13EE_028G1	S13EE_028MH	S13EE_022MH	37.90524	18
S13EE_022G1	S13EE_022MH	S13EE_025MH	22.09807	8
S13GG_024G1	S13GG_024MH	S13GG_032MH	74.84546	8
S13GG_062G1	S13GG_062DE	S13GG_013MH	75.11390	8
S13GG_063G1	S13GG_063DE	S13GG_024MH	229.896	8
S13GG_010G1	S13GG_010MH	S13EE_028MH	167.2049	18
S13GG_017G1	S13GG_017MH	S13GG_036MH	227.2486	18
S13GG_018G1	S13GG_018MH	S13GG_010MH	69.63516	8
S13GG_065G1	S13GG_065DE	S13EE_022MH	96.68937	18
S13GG_047G1	S13GG_047MH	S13GG_005MH	156.4272	18
S13GG_013G1	S13GG_013MH	S13GG_005MH	128.8077	8
S13GG_019G1	S13GG_019MH	S13GG_032MH	23.41611	8

### Observations & Photos

---

No smoke was observed during this test.

